

Aruba Instant 6.5.4.25



Release Notes

Copyright Information

© Copyright 2023 Hewlett Packard Enterprise Development LP.

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses. A complete machine-readable copy of the source code corresponding to such code is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company
6280 America Center Drive
San Jose, CA 95002
USA

Contents	3
Revision History	4
Release Overview	5
Supported Browsers	5
Important Updates	6
Contacting Support	6
What's New	8
Regulatory Updates	9
Resolved Issues	10
Known Issues	11
Upgrading an Instant AP	16
Upgrading an Instant AP and Image Server	16
Upgrading an Instant AP Using Automatic Image Check	18
Upgrading an Instant AP Image Using CLI	19

Revision History

The following table provides the revision history of this document.

Table 1: Revision History

Revision	Change Description
Revision 01	Initial release.

This Aruba Instant release notes includes the following topics:

- [What's New on page 8](#)
- [Regulatory Updates on page 9](#)
- [Resolved Issues on page 10](#)
- [Known Issues on page 11](#)
- [Upgrading an Instant AP on page 16](#)

For list of terms, refer to the [Glossary](#).



For information regarding prior releases, refer to the corresponding Release Notes on asp.arubanetworks.com.

Supported Browsers

The following browsers are officially supported for use with the Aruba Instant WebUI:

- Microsoft Internet Explorer 10.x and 11 on Windows 7 and Windows 8
- Mozilla Firefox 23 or later on Windows Vista, Windows 7, and macOS
- Apple Safari 5.1.7 or later on macOS
- Google Chrome 51.0.2704.103 m (64-bit)
- Microsoft Edge 25.10586.0.0 and Microsoft Edge HTML 13.10586

Important Updates

DPI

Starting from Instant 6.5.0.0-4.3.0.0 onwards, DPI is not supported on IAP-103, RAP-108, and RAP-109 due to the existing memory limitations. The last release with full feature support for these platforms is Instant 6.4.x.x-4.2.x.x.

If you have deployed IAP-103, RAP-108, or RAP-109 and require DPI functionality, ensure that you remain on Instant 6.4.x.x-4.2.x.x or earlier versions. However, if you are willing to disable DPI functionality, upgrade to Instant 6.5.0.0-4.3.0.0 or later releases.

IP-Mode

The IP-mode default value changes to **v4 only** in the Instant 6.5.4.0 release version. This change in value causes a mismatch warning for AirWave and Central customers that use a template file for configuration. We recommend you to change the template file in AirWave and Central to fix this mismatch. AirWave and Central UI users, please upgrade your respective versions.



The mismatch occurs only if the release versions used before the upgrade are from Instant 6.5.2.0 to Instant 6.5.3.1. There will be no mismatch if the release version used before the upgrade is earlier than Instant 6.5.2.0 or later than Instant 6.5.3.1.

Contacting Support

Table 2: *Contact Information*

Main Site	arubanetworks.com
Support Site	https://asp.arubanetworks.com/
Airheads Social Forums and Knowledge Base	community.arubanetworks.com
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200
International Telephone	arubanetworks.com/support-services/contact-support/

Software Licensing Site	lms.arubanetworks.com
End-of-life Information	arubanetworks.com/support-services/end-of-life/
Security Incident Response Team	Site: arubanetworks.com/support-services/security-bulletins/ Email: aruba-sirt@hpe.com

New Features and Enhancements

There are no new features or enhancements introduced in this release.

This chapter describes the regulatory updates in Aruba Instant 6.5.x.



Contact your local Aruba sales representative about device availability and support for your country.

Periodic regulatory changes may require modifications to the list of channels supported by an Instant AP. For a complete list of channels supported by an Instant AP using a specific country domain, access the Instant AP CLI and execute the **show ap allowed-channels** command.

The following DRT file version is part of this release:

- DRT-1.0_85798

For a complete list of countries certified with different AP models, refer to the DRT Release Notes at asp.arubanetworks.com.



The FCC has changed the rules for operation in all of the 5 GHz bands. For more information, refer to the *FCC DFS Regulatory Change Impact and Resolution Plan - Support Advisory* available in asp.arubanetworks.com.

The following issues are resolved in this release.

Table 3: Resolved Issues in Instant 6.5.4.25

Bug ID	Description	Component	Platform	Reported Version
AOS-236847	<p>Symptom: The 210 Series, 220 Series, and 270 Series access points were blocked when attempting to scan specific channels. The fix ensures that an AP only scans and moves to channels that are allowed.</p> <p>Scenario: This issue occurred because the regulatory file allowed the Instant AP to operate in channels that were not allocated to it. This issue was observed in APs running Aruba Instant 6.5.4.25 or later versions.</p>	AP-Wireless	210 Series, 220 Series, and 270 Series access points	Aruba Instant 8.10.0.1

This chapter describes the known and outstanding issues identified in this release.



We have migrated to a new defect tracking tool. Some bugs are listed with the new bug ID, which is prefixed by AOS.

Table 4: Known Issues in Instant 6.5.4.25

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-140975 AOS-175951 AOS-180447	171577 168254 189776	Symptom: An Instant AP reboots unexpectedly. The log file lists the reason for the event as: Reboot caused by kernel panic: Take care of the HOST ASSERT first. Scenario: This issue occurs when the messaging between the WLAN firmware and UMAC goes out of sync. This issue is observed in member APs in an Instant cluster running Aruba Instant 6.5.1.0-4.3.1.2 or later versions.	Wi-Fi Driver	All platforms	Aruba Instant 6.5.1.0-4.3.1.2
AOS-174756 AOS-175463 AOS-175467	161239 165458 165474	Symptom: An Instant AP is unable to reach the Central server. Scenario: This issue occurs when the Instant software is downgraded from Instant 6.5.3.0 to Instant 6.5.1.0-4.3.1.3 because of the default value of the ip-mode parameter. This issue is observed in APs running Aruba Instant 6.5.1.0-4.3.1.3 or later versions.	IPv6	All platforms	Aruba Instant 6.5.1.0-4.3.1.3
AOS-176463	170478	Symptom: An Instant AP delays the ICMP response from the wired server to a wireless client connected to the AP on the 2.4 GHz radio. Scenario: This issue is observed in APs running Aruba Instant 6.5.3.0 or later versions.	Wi-Fi Driver	All platforms	Aruba Instant 6.5.3.0

Table 4: Known Issues in Instant 6.5.4.25

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-176815	171948	Symptom: An Instant AP sends DLNA responses with the IP address of the DLNA server as the source IP address, causing a network outage. Scenario: This issue occurs when the DLNA response packets reach the DLNA server with its IP address as the source IP address and the DLNA server falsely detects a network loop. This issue is observed in APs running Aruba Instant 6.5.4.3 or later versions.	AirGroup	All platforms	Aruba Instant 6.5.4.3
AOS-176934	172460	Symptom: An Instant AP logs multiple checksum-mismatch alerts. Scenario: This issue occurs because of a mismatch in the authentication server configuration in the Instant AP. This issue is observed in APs running Aruba Instant 6.5.4.2 or later versions.	VC Management	All platforms	Aruba Instant 6.5.4.2
AOS-176946	172554	Symptom: Instant APs in a cluster are displaying huge volumes of the error message: KERNEL(AWAP-AM-US-Mil-3-1-F36_Shipping@10.249.1.192): [8081.995439] protocol 0000 is buggy, dev br0 nh=d92120d8 d=d9212070 =d92120cb. Scenario: This issue is observed in APs running Aruba Instant 6.5.3.3 or later versions.	Platform	All platforms	Aruba Instant 6.5.3.3
AOS-177621	175913	Symptom: An Instant AP crashes and reboots unexpectedly. The log file lists the reason for the event as: Reboot Time and Cause: Reboot caused by kernel panic: Fatal exception in interrupt and Reboot caused by kernel panic: softlockup: hung task. Scenario: This issue is observed in IAP-315 access points running Aruba Instant 6.5.4.3 or later versions.	Wi-Fi Driver	IAP-315 access points	Aruba Instant 6.5.4.3
AOS-177624	175958	Symptom: An Instant AP does not receive an IP address when the uplink fails over to LTE. Scenario: This issue occurs when the datapath route cache entry is set to 3G/4G fails. This issue is observed in APs running Aruba Instant 6.5.3.3 or later versions.	3G/4G Management	All platforms	Aruba Instant 6.5.3.3

Table 4: Known Issues in Instant 6.5.4.25

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-177963	177761	Symptom: Users are unable to delete the clients that are dynamically blacklisted after an authentication failure. Scenario: This issue is observed in APs running Aruba Instant 6.5.4.0 or later versions.	Authentication	All platforms	Aruba Instant 6.5.4.0
AOS-178111	178761	Symptom: An Instant AP displays an error message: domain name has reach the max number when a user tries to add a new rule. Scenario: This issue is observed in APs running Aruba Instant 6.5.4.6 or later versions.	Datapath	All platforms	Aruba Instant 6.5.4.6
AOS-178134	178915	Symptom: DNS and HTTP traffic are not categorized by the Instant AP. Scenario: This issue is observed in APs running Aruba Instant 6.5.4.3 or later versions.	AppRF	All platforms	Aruba Instant 6.5.4.3
AOS-178233	179493	Symptom: A member Instant AP stops communicating to Central, continues to communicate with the conductor Instant AP, and switches to local management. Scenario: This issue occurs when PAPI fails between a member Instant AP and the conductor Instant AP. This issue is observed in APs running Aruba Instant 6.5.4.4 or later versions.	Central	All platforms	Aruba Instant 6.5.4.4
AOS-178688	180846	Symptom: An Instant AP performs source NATing of traffic with its inner IP address and a client is assigned an IP address from the distributed L3 scope. Scenario: This issue is observed in APs running Aruba Instant 6.5.4.7 or later versions.	AppRF	All platforms	Aruba Instant 6.5.4.7
AOS-179683	185975	Symptom: Some characters in the running configuration are missing when the entire running configuration is copied and pasted into the CLI access. Scenario: This issue occurs only when the AP console is used and not SSH. This issue is observed in APs running Aruba Instant 6.5.4.5 or later versions.	Configuration	All platforms	Instant 6.5.4.5

Table 4: Known Issues in Instant 6.5.4.25

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-180288	188738	Symptom: An Instant AP crashes and reboots unexpectedly. The log file lists the reason for the event as: Reboot caused by kernel panic: Fatal exception in interrupt. Scenario: This issue is observed in IAP-315 and IAP-325 access points running Aruba Instant 6.5.4.7 or later versions.	Platform	IAP-315 and IAP-325 access points	Aruba Instant 6.5.4.7
AOS-180904	191443	Symptom: Users are unable to hear audio in a VoIP call after 10 minutes. Scenario: This issue occurs if the SIP server is outside the client's network and the Instant AP performs NAT on the SIP control session packets. This issue is observed in APs running Aruba Instant 6.5.4.7 or later versions. Workaround: Place the SIP server in the same network as the SIP clients. This ensures that NAT is not performed on the SIP control session packets.	VC Management	All platforms	Aruba Instant 6.5.4.7
AOS-181453	193816	Symptom: An Instant AP reboots unexpectedly. The log file lists the reason as: Reboot caused by kernel panic: Fatal exception. Scenario: This issue occurs due to a memory access issue in the Instant AP. This issue is observed in APs running Aruba Instant 6.5.4.9 or later versions.	Datapath	All platforms	Aruba Instant 6.5.4.9
AOS-181829	195194	Symptom: Downstream traffic for a wireless client from the old VLAN is still sent to the old VLAN after the client changes over to a different VLAN and SSID on the same AP. Scenario: This issue is observed in APs running Aruba Instant 6.5.4.9 or later versions.	Datapath	All platforms	Aruba Instant 6.5.4.9

Table 4: Known Issues in Instant 6.5.4.25

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-182578	—	<p>Symptom: Certificates with an encrypted private key fail to upload and return the following error message: <code>rsa_key_validation_error</code>.</p> <p>Scenario: This issue occurs when the encryption type is aes-128-cbc, aes-192-cbc, or aes-256-cbc. This issue is observed in APs running Aruba Instant 6.5.4.8 or later versions.</p> <p>Workaround: Upload the certificate using a decrypted private key.</p>	Captive Portal	All platforms	Aruba Instant 6.5.4.8
AOS-187350	—	<p>Symptom: An Instant AP does not update the client's username received from the ClearPass server.</p> <p>Scenario: This issue occurs when captive portal authentication is used. This issue is observed in APs running Aruba Instant 6.5.4.0 or later versions.</p>	Authentication	All platforms	Aruba Instant 6.5.4.0
AOS-209870	—	<p>Symptom: An IAP-205 access point fails to add new client entries to the Analytics and Location Engine.</p> <p>Scenario: This issue occurs when the potential station list of the AP reaches the maximum threshold. This issue is observed in IAP-205 access points running Aruba Instant 6.5.4.17 or later versions.</p>	IDS	IAP-205 access points	Aruba Instant 6.5.4.17
AOS-218235	—	<p>Symptom: The controller logs random IP and MAC pairing information in its user table in an IAP-VPN deployment.</p> <p>Scenario: This issue occurs when clients roam to a different Instant AP in the cluster before completing the DNS process with the source Instant AP. This issue is observed in APs running Aruba Instant 6.5.4.18 or later versions.</p>	IAPMgr	All platforms	Aruba Instant 6.5.4.18
AOS-240459	—	<p>Symptom: Static IP addresses of locally managed Instant APs are changed to DHCP IP addresses if the assigned default is unreachable.</p> <p>Scenario: This issue is observed in APs running Aruba Instant 6.5.0.0 or later versions.</p>	Activate	All platforms	Aruba Instant 6.5.4.20

This chapter describes the Instant software upgrade procedures and the different methods for upgrading the image on the Instant AP.



While upgrading an Instant AP, you can use the image check feature to allow the Instant AP to find new software image versions available on a cloud-based image server hosted and maintained by Aruba, a Hewlett Packard Enterprise company. The location of the image server is fixed and cannot be changed by the user. The image server is loaded with the latest versions of the Instant software.

Topics in this chapter include:

- [Upgrading an Instant AP and Image Server on page 16](#)
- [Upgrading an Instant AP Using Automatic Image Check on page 18](#)
- [Upgrading an Instant AP Image Using CLI on page 19](#)

Upgrading an Instant AP and Image Server

Instant supports mixed Instant AP-class Instant deployment with all Instant APs as part of the same virtual controller cluster.

Image Management Using AirWave

If the multiclass Instant AP network is managed by AirWave, image upgrades can only be done through the AirWave UI. The Instant AP images for different classes must be uploaded on the AMP server. When new Instant APs joining the network need to synchronize their software with the version running on the virtual controller, and if the new Instant AP belongs to a different class, the image file for the new Instant AP is provided by AirWave. If AirWave does not have the appropriate image file, the new Instant AP will not be able to join the network.



The virtual controller communicates with the AirWave server if AirWave is configured. If AirWave is not configured on the Instant AP, the image is requested from the Image server.

Image Management Using Cloud Server

If the multiclass Instant AP network is not managed by AirWave, image upgrades can be done through the Cloud-Based Image Check feature. When a new Instant AP joining the network needs to synchronize its software version with the version on the VC and if the new Instant AP belongs to a different class, the image file for the new Instant AP is provided by the cloud server.

Configuring HTTP Proxy on an Instant AP


If your network requires a proxy server for Internet access, ensure that you configure the HTTP proxy on the Instant AP to download the image from the cloud server. After setting up the HTTP proxy settings, the Instant AP connects to the Activate server, AMP, Central, or OpenDNS server through a secure HTTP connection. You can also exempt certain applications from using the HTTP proxy (configured on an Instant AP) by providing their host name or IP address under exceptions.

In the WebUI

To configure the HTTP proxy settings:

1. Navigate to **System > Proxy**. The Proxy configuration window is displayed.

Figure 1 *Proxy Configuration Window*



2. Enter the HTTP proxy server IP address in the **Server** text box.
3. Enter the port number in the **Port** text box.
4. If you do not want the HTTP proxy to be applied for a particular host, click **New** to enter that IP address or domain name of that host in the **Exceptions** section.

In the CLI

To configure the HTTP proxy settings:

```
(Instant AP) (config) # proxy server 192.0.2.1 8080
(Instant AP) (config) # proxy exception 192.0.2.2
(Instant AP) (config) # end
(Instant AP) # commit apply
```

Upgrading an Instant AP Using Automatic Image Check

You can upgrade an Instant AP by using the Automatic Image Check feature. The automatic image checks are performed once, as soon as the Instant AP boots up and every week thereafter.

If the image check locates a new version of the Instant software on the image server, the [New version available](#) link is displayed on the Instant main window.



If AirWave is configured, the automatic image check is disabled.

To check for a new version on the image server in the cloud:

1. Go to **Maintenance > Automatic > Check for New Version**. After the image check is completed, one of the following messages is displayed:
 - No new version available—If there is no new version available.
 - Image server timed out—Connection or session between the image server and the Instant AP is timed out.
 - Image server failure—If the image server does not respond.
 - A new image version found—If a new image version is found.
2. If a new version is found, the **Upgrade Now** button becomes available and the version number is displayed.
3. Click **Upgrade Now**.

The Instant AP downloads the image from the server, saves it to flash, and reboots. Depending on the progress and success of the upgrade, one of the following messages is displayed:

- Upgrading—While image upgrading is in progress.
- Upgrade successful—When the upgrade is successful.
- Upgrade failed—When the upgrade fails.

If the upgrade fails and an error message is displayed, retry upgrading the Instant AP.

Upgrading to a New Version Manually

If the Automatic Image Check feature is disabled, you can manually obtain an image file from a local file system or from a TFTP or HTTP URL.

The following procedure describes how to manually check for a new firmware image version and obtain an image file:

1. Navigate to **Maintenance > Firmware**.
2. Under Manual section, perform the following steps:
 - Select the Image file option. This method is only available for single-class Instant APs.
The following examples describe the image file format for different Instant AP models:
 - For AP-203H—ArubaInstant_Vela_6.5.4.x_xxxx

- For IAP-334/335—ArubaInstant_Lupus_6.5.4.x_xxxx
- For IAP-314/315 and IAP-324/325—ArubaInstant_Hercules_6.5.4.x_xxxx
- For IAP-224/225, IAP-228, IAP-214/215, IAP-274/275, IAP-277—ArubaInstant_Centaurus_6.5.4.x_xxxx
- For IAP-204/205 and IAP-205H—ArubaInstant_Taurus_6.5.4.x_xxxx
- For RAP-155/155P—ArubaInstant_Aries_6.5.4.x_xxxx
- For RAP-108/109, IAP-103, and IAP-114/115—ArubaInstant_Pegasus_6.5.4.x_xxxx

■ Select the **Image URL** option. Select this option to obtain an image file from a HTTP, TFTP, or FTP URL.

- HTTP - `http://<IP-address>/<image-file>`. For example, `http://<IP-address>/ArubaInstant_Hercules_6.5.4.x_xxxx`
- TFTP - `tftp://<IP-address>/<image-file>`. For example, `tftp://<IP-address>/ArubaInstant_Hercules_6.5.4.x_xxxx`
- FTP - `ftp://<IP-address>/<image-file>`. For example, `ftp://<IP-address>/ArubaInstant_Hercules_6.5.4.x_xxxx`
- FTP - `ftp://<user name:password>@<IP-address>/<image-file>`. For example, `ftp://<aruba:123456>@<IP-address>/ArubaInstant_Hercules_6.5.4.x_xxxx`



The FTP server supports both **anonymous** and **username:password** login methods.

Multiclass Instant APs can be upgraded only in the URL format, not in the local image file format.

3. Clear the **Reboot all APs after upgrade** check box if required. The **Reboot all APs after upgrade** check box is selected by default to allow the Instant APs to reboot automatically after a successful upgrade. To reboot the Instant AP at a later time, clear the **Reboot all Instant APs after upgrade** check box.
4. Click **Upgrade Now** to upgrade the Instant AP to the newer version.

Upgrading an Instant AP Image Using CLI

To upgrade an image using a HTTP, TFTP, or FTP URL:

```
(Instant AP) # upgrade-image <ftp/tftp/http-URL>
```

To upgrade an image by using the username and password in the FTP URL :

```
(Instant AP) # upgrade-image ftp://Aruba:123456@192.0.2.7/ArubaInstant_Hercules_6.5.4.x_xxxx
```

To upgrade an image without rebooting the Instant AP:

```
(Instant AP) # upgrade-image2-no-reboot <ftp/tftp/http-URL>
```

To view the upgrade information:

```
(Instant AP) # show upgrade info
Image Upgrade Progress
-----
Mac IP Address AP Class Status Image Info Error Detail
-----
```

```
d8:c7:c8:c4:42:98 10.17.101.1 Hercules image-ok image file none
Auto reboot :enable
Use external URL :disable
```