

# **HPE Aruba Networking**

## **Wireless Operating System**

### **8.10.0.20 Release Notes**



**Hewlett Packard  
Enterprise**

## **Copyright Information**

© Copyright 2025 Hewlett Packard Enterprise Development LP.

## **Open Source Code**

This product includes code licensed under certain open source licenses which require source compliance. The corresponding source for these components is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, please check if the code is available in the HPE Software Center at <https://myenterpriselicense.hpe.com/cwp-ui/software> but, if not, send a written request for specific software version and product for which you want the open source code. Along with the request, please send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company  
Attn: General Counsel  
WW Corporate Headquarters  
1701 E Mossy Oaks Rd, Spring, TX 77389  
United States of America



---

<b>Contents</b>	<b>3</b>
<b>Revision History</b>	<b>4</b>
<b>Release Overview</b>	<b>5</b>
Important	5
Related Documents	5
Supported Browsers	6
Terminology Change	6
Contacting Support	6
<b>What's New in AOS-8.10.0.20</b>	<b>8</b>
<b>Supported Platforms</b>	<b>9</b>
<b>Regulatory Updates</b>	<b>13</b>
<b>Resolved Issues in AOS-8.10.0.20</b>	<b>14</b>
<b>Known Issues in AOS-8.10.0.20</b>	<b>17</b>
<b>Limitations in AOS-8.10.x</b>	<b>23</b>
<b>Upgrade Procedure</b>	<b>25</b>
Important Points to Remember	25
RAM and FLASH Storage Requirements	26
Low Free Flash Memory	26
Backing up Critical Data	29
Upgrading AOS-8	30
Verifying the AOS-8 Upgrade	32
Downgrading AOS-8	32
Before Calling Technical Support	34

# Chapter 1

## Revision History

---

The following table lists the revision numbers and the corresponding changes that were made in this release:

**Table 1:** *Revision History*

Revision	Change Description
Revision 01	Initial release.

# Chapter 2

## Release Overview

---

These AOS-8 release notes include the following topics:

- New Features and Enhancements
- Supported Platforms
- Regulatory Updates
- Resolved Issues
- Known Issues and Limitations
- Upgrade Procedure

## Important

- Upgrading from AOS-8.10.0.6 or earlier versions on 9000 Series and 9200 Series controllers will take longer than usual as we will be automatically upgrading the BIOS version to support additional functionality in the future. This upgrade is estimated to take up to 15 minutes and should not be interrupted for any reason. Power failures and interruptions during the upgrade may result in the controller being unusable. Please use caution and plan accordingly.



Cluster Rolling Upgrade is not supported when a BIOS upgrade is required. AOS-8 must be manually upgraded for these controllers. In a (very rare) scenario where, post reload command, the unit does not come up in 15-20 minutes, apply power cycle only once and wait for a minimum of 15 minutes without re-applying power cycle again.

- As mandated by the Wi-Fi Alliance, AOS-8.10.0.0 and later versions require Hash-to-Element (H2E) for 6 GHz WPA3-SAE connections. H2E is supported on Android 12 or later versions, Linux `wpa_supplicant` version 2.10 or later versions, macOS Catalina or later versions, Windows 11 or later versions. Users must upgrade their clients to support successful 6 GHz WPA3-SAE connections.
- The factory-default image of APs introduced in AOS-8.9.0.0 or later versions use **aruba-conductor** as the host name instead of **aruba-master** to identify a target managed device or stand-alone controller during DNS discovery. However, the factory-default image of APs that were introduced prior to AOS-8.9.0.0 still use **aruba-master** during DNS discovery. The usage of **aruba-conductor** is to align with the Inclusive Language Initiative.

## Related Documents

The following guides are part of the complete documentation for the Aruba user-centric network:

- *AOS-8 Getting Started Guide*
- *AOS-8 User Guide*
- *AOS-8 CLI Reference Guide*
- *AOS-8 API Guide*
- *Aruba Mobility Conductor Licensing Guide*
- *Aruba Virtual Appliance Installation Guide*

- Aruba AP Software Quick Start Guide

## Supported Browsers

The following browsers are officially supported for use with the AOS-8 WebUI:

Web Browser	Operating System
Microsoft Edge (Microsoft Edge 92.0.902.62 and Microsoft EdgeHTML 18.19041) or later	<ul style="list-style-type: none"> <li>■ Windows 10 or later</li> <li>■ macOS</li> </ul>
Firefox 107.0.1 or later	<ul style="list-style-type: none"> <li>■ Windows 10 or later</li> <li>■ macOS</li> </ul>
Apple Safari 15.4 (17613.17.1.13) or later	<ul style="list-style-type: none"> <li>■ macOS</li> </ul>
Google Chrome 108.0.5359.71 or later	<ul style="list-style-type: none"> <li>■ Windows 10 or later</li> <li>■ macOS</li> </ul>

## Terminology Change

As part of advancing HPE's commitment to racial justice, we are taking a much-needed step in overhauling HPE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our HPE culture and moving forward, Aruba will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

## Contacting Support

**Table 2:** *Contact Information*

Main Site	<a href="http://arubanetworking.hpe.com">arubanetworking.hpe.com</a>
Support Site	<a href="http://networkingsupport.hpe.com">networkingsupport.hpe.com</a>
Airheads Social Forums and Knowledge Base	<a href="http://community.arubanetworks.com">community.arubanetworks.com</a>
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200

---

International Telephone	<a href="http://arubanetworks.com/support-services/contact-support">arubanetworks.com/support-services/contact-support</a>
Software Licensing Site	<a href="http://lms.arubanetworks.com">lms.arubanetworks.com</a>
End-of-life Information	<a href="http://arubanetworks.com/support-services/end-of-life">arubanetworks.com/support-services/end-of-life</a>
Security Incident Response Team	Site: <a href="http://arubanetworks.com/support-services/security-bulletins">arubanetworks.com/support-services/security-bulletins</a> Email: <a href="mailto:aruba-sirt@hpe.com">aruba-sirt@hpe.com</a>

---

## Chapter 3

# What's New in AOS-8.10.0.20

---

There are no new features, enhancements or behavioral changes introduced in this release.

# Chapter 4

## Supported Platforms

---

This section displays the supported platforms in AOS-8.x. The **minimum version supported** column displays the minimum AOS-8.x version that can be run on a platform. The **latest version supported** column displays the newest AOS-8.x version that can be run on a certain device. Patch releases do not affect platform support. For example, a device which **latest supported version** is 8.10.0.x can run on any 8.10.0.x version, such as 8.10.0.2 or 8.10.0.10.

### Mobility Conductor Platforms

Mobility Conductor		AOS-8.x Versions Supported	
Conductor Family	Conductor Model	Minimum	Latest
Hardware Mobility Conductor	MCR-HW-1K, MCR-HW-5K, MCR-HW-10K	8.1.0.x	8.13.x.x
Virtual Mobility Conductor	MCR-VA-500, MCR-VA-1K, MCR-VA-5K, MCR-VA-10K	8.0.0.x	8.13.x.x
	MCR-VA-50	8.1.0.x	8.13.x.x

### Mobility Controller Platforms

Mobility Controllers		AOS-8.x Versions Supported	
Controller Family	Controller Model	Minimum	Latest
9100 Series	9106	8.13.1.0	8.13.x.x
9200 Series	9240	8.10.0.x	8.13.x.x
9000 Series	9012	8.7.0.x	8.13.x.x
	9004	8.5.0.x	8.13.x.x
7200 Series	7280	8.3.0.x	8.13.x.x
	7205, 7210, 7220, 7240, 7240XM	8.0.0.x	8.13.x.x
7000 Series	7005, 7008, 7010, 7024, 7030	8.0.0.x	8.13.x.x
Virtual Mobility Controllers	MC-VA-50, MC-VA-250, MC-VA-1K	8.0.0.x	8.13.x.x
	MC-VA-10	8.4.0.x	8.13.x.x

### Access Point Platforms

## Access Points

## AOS-8.x Versions Supported

AP Family	AP Series	AP Model	Minimum	Latest
6xx	670 Series	AP-675, AP-675EX, AP-677, AP-677EX, AP-679, AP-679EX	8.12.0.x	8.13.x.x
		AP-655	8.10.0.x	8.13.x.x
	650 Series	AP-654	8.11.2.x	8.13.x.x
		AP-635	8.9.0.x	8.13.x.x
	630 Series	AP-634	8.11.2.x	8.13.x.x
		AP-615	8.11.0.x	8.13.x.x
	600 Series	AP-605H	8.12.0.x	8.13.x.x
	580 Series	AP-584, AP-585, AP-585EX, AP-587, AP-587EX	8.10.0.x	8.13.x.x
		AP-574, AP-575, AP-577, AP-575EX, AP-577EX	8.7.0.x	8.13.x.x
		AP-565, AP-567, AP-565EX, AP-567EX	8.7.1.x	8.13.x.x
		AP-555	8.5.0.x	8.13.x.x
		AP-534, AP-535	8.5.0.x	8.13.x.x
5xx	510 Series	AP-518	8.7.0.x	8.13.x.x
		AP-514, AP-515	8.4.0.x	8.13.x.x
	500 Series	AP-504, AP-505	8.6.0.x	8.13.x.x
		AP-505H, AP-505HR	8.7.0.x	8.13.x.x
		AP-503H, AP-503HR	8.7.1.x	8.13.x.x
		AP-503	8.11.1.x	8.13.x.x

## Access Points

## AOS-8.x Versions Supported

AP Family	AP Series	AP Model	Minimum	Latest
3xx	380 Series	AP-387	8.4.0.x	8.10.0.x
	370 Series	AP-374, AP-375, AP-377, AP-375EX, AP-377EX, AP-375ATEX	8.3.0.x	8.13.x.x
	360 Series	AP-365, AP-367	8.3.0.x	8.13.x.x
	340 Series	AP-344, AP-345	8.3.0.x	8.10.0.x
	330 Series	AP-334, AP-335	8.1.0.x	8.10.0.x
	320 Series	AP-324, AP-325	8.0.0.x	8.10.0.x
	310 Series	AP-318	8.3.0.x	8.13.x.x
		AP-314, AP-315	8.1.0.x	8.13.x.x
	300 Series	AP-304, AP-305	8.1.0.x	8.13.x.x
		AP-303H, AP-303HR	8.2.0.x	8.13.x.x
		AP-303P	8.4.0.x	8.13.x.x
		AP-303	8.3.0.x	8.13.x.x
2xx	270 Series	AP-274, AP-275, AP-277	8.0.0.x	8.10.0.x
	220 Series	AP-224, AP-225, AP-228	8.0.0.x	8.10.0.x
	210 Series	AP-214, AP-215	8.0.0.x	8.10.0.x
	200 Series	AP-207	8.1.0.x	8.10.0.x
		AP-204, AP-205, AP-205H	8.0.0.x	8.10.0.x
		AP-203H, AP-203R, AP-203RP	8.2.0.x	8.10.0.x

## Access Points

## AOS-8.x Versions Supported

AP Family	AP Series	AP Model	Minimum	Latest
1xx	170 Series	AP-175AC, AP-175AC-F1, AP-175DC, AP-175DC-F1, AP-175P, AP-175P-F1	8.0.0.x	8.6.0.x
		AP-134, AP-135	8.0.0.x	8.6.0.x
	110 Series	AP-114, AP-115	8.0.0.x	8.6.0.x
		AP-103, AP-104, AP-105	8.0.0.x	8.6.0.x
		AP-103H	8.0.0.x	8.3.0.x
9x	90 Series	AP-92, AP-93, AP-93H	8.0.0.x	8.2.0.x

# Chapter 5

## Regulatory Updates

---

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release. Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the controller Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at [networkingsupport.hpe.com](http://networkingsupport.hpe.com).

The following DRT file version is part of this release:

- DRT-1.0\_93760

# Chapter 6

## Resolved Issues in AOS-8.10.0.20

---

This chapter describes the resolved issues in this release.

**Table 3:** Resolved Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-250835	During STA-to-AP ranging, traffic dropped to 0 Mbps instead of maintaining a steady throughput, triggering a PSM watchdog crash. This was caused by corruption in the beacon frames due to the capture sample size. The fix ensures that processes work as expected. This issue was observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-252007	Loss of data transmission was observed in some access points. This occurred due to memory issues in non-AMSDU AMPDU traffic for some time. The fix ensures that the APs work as expected. This issue was observed in AP-515 and AP-505 access points running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-255253 AOS-206579 AOS-261705 AOS-263692	Some clients did not display the values for <b>ACTIVE CONTROLLER</b> and <b>STANDBY CONTROLLER</b> under the <b>Dashboard &gt; Overview</b> page of the WebUI. This issue occurred due to UAC and SUAC values not being populated before the AMON message was generated. The fix ensures that the process works as expected. This issue was observed in controllers running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11
AOS-257844	The <b>Dashboard &gt; Infrastructure &gt; Access Devices</b> page of the WebUI did not populate any information and showed an <b>Error retrieving information</b> message. This occurred due to SC-MON receiving PAPI messages larger than the buffer size. This issue was observed in devices running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-260657	The output of the <b>show wms rogue-ap list</b> Web API command displayed incorrect information due to hidden or control characters in ESSIDs, which interfered with the XML-to-JSON conversion process. When this occurred, the system logged the raw XML data. The fix ensures that the process works as expected. This issue was observed in devices running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-261894	Some AP-635 access points running AOS-8.10.0.14 or later versions experienced beacon stuck events and watchdog resets, causing random user disconnections. This occurred when DPD calibration mode failed to exit properly and the AP remained active, causing high channel utilization.	AOS-8.10.0.14
AOS-263652	Some AP-655 access points running AOS-8.10.0.15 or later versions experienced a packet loss increase on the 2.4 GHz channel. This issue occurred when uploading multicast packets to a wired server. The fix ensures packet loss is restored to expected levels.	AOS-8.10.0.15

**Table 3:** Resolved Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-263686	Some controllers running AOS-8.10.0.14 or later versions displayed repeated syslog messages stating <b>PAPI_open_udp_socket: UDP bind call failed: Address already in use 8450</b> . The issue occurred occasionally on an idle system or when users ran the <b>show memory debug verbose</b> command from multiple SSH sessions. The fix ensures that the process works as expected.	AOS-8.10.0.14
AOS-263834	Users on an internal SSID trying to connect through a 7280 controller were not redirected to the Captive Portal page. This issue occurred due to <b>tunnel-ids</b> not being updated in the ESI group. The fix ensures that users are successfully redirected to the Captive Portal page. This issue was observed in controllers running AOS-8.10.0.15 or later versions.	AOS-8.10.0.15
AOS-264440	When 802.11r was enabled, users failed to respond to <b>WPA-Key1</b> during unicast key rotation, which resulted in deauthentication and disconnection from the AP, causing the users to initiate a reauthentication process for a new connection to the AP. This occurred due to a mismatch in the MIC used in the key exchange process. The fix ensures that APs work as expected. This issue was observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.11.2.2
AOS-264694	When configured in CAP mode and connected to unrestricted controllers, some AP-335 access points failed to adopt the <b>US</b> country code after an image update. This issue occurred due to missing factory-programmed country codes on early devices. The fix ensures that APs can be configured with the <b>US</b> country code. This issue was observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.10.0.13
AOS-264903	Clients connected to a WPA3-AES-CCM-128 SSID configured with 802.11r in tunnel mode intermittently failed to pass traffic after roaming to a different AP. Traffic resumed after typically 10 to 15 minutes or until the clients roamed again to another AP. This occurred because clients were unable to complete the DHCP process, hence not getting an IP address post-roaming. The fix ensures that APs handle DHCP and roaming transitions correctly. This issue was observed in devices running AOS-8.10.0.16 or later versions.	AOS-8.10.0.16
AOS-265370	Some controllers showed the <b>fw_agg_sess_aggregate: session denied flag after aggregation 0</b> log multiple times. The fix ensures that controllers work as expected. This issue was observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.10.0.15
AOS-265378	When <b>app-perf-monitoring</b> was enabled, controllers experienced high SP CPU utilization and latency due to spikes in the HTTPS sessions to destination IPs. This occurred because the firewall aggregation process was slowed down by errors in addition and lookup function. The fix ensures that controllers work as expected. This issue was observed in devices running AOS-8.10.0.15 or later versions.	AOS-8.10.0.15
AOS-265626 AOS-267720	AirGroup servers were missing hostnames and MAC addresses were displayed instead in the <b>Dashboard &gt; Services</b> page of the WebUI, in contrast the CLI displayed properly. This happened due to incorrect properties being set while updating WebUI values. The fix ensures the correct values are displayed in the WebUI. This issue was observed in devices running AOS-8.10.0.10 or later versions.	AOS-8.10.0.10

**Table 3:** Resolved Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-265868	After an image upgrade, some users encountered unexpected alerts on controllers equipped with two or more power supply units. The WebUI page displayed the message <b>Power supply 1 is not supported, please remove it.</b> The fix ensures that controllers work as expected. This issue was observed in devices running AOS-8.10.0.15 or later versions.	AOS-8.10.0.15
AOS-266047	Some managed devices were unreachable when users tried to login through the WebUI, SSH or Console sessions. This occurred due to inactive processes consuming the limited session slots. This issue was observed in controllers running AOS-8.10.0.16 or later versions.	AOS-8.10.0.16
AOS-266066	9240 controllers crashed and rebooted due to an issue on the datapath decryption flow. The log files listed the reason for the event as <b>Reboot Cause: Datapath timeout (Intent:cause: 86:56).</b> The fix ensures that the process works as expected. This issue was observed in controllers running AOS-8.10.0.17 or later versions.	AOS-8.10.0.17
AOS-266210	After a cluster failover, APs were unable to send traffic because they were still using the Virtual Redundancy Protocol (VRRP) address associated with the original primary cluster. The fix ensures that APs work as expected. This issue was observed in devices running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-266241	The <b>nbapi-helper</b> process crashed due to a memory leak. The fix ensures that the process works as expected. This issue was observed in Mobility Conductors running AOS-8.10.0.15 or later versions.	AOS-8.10.0.17
AOS-266738	When trying to upgrade to AOS-8.13.1.0 using the <b>copy scp</b> command, an <b>Error : Volume was not properly unmounted. Some data may be corrupt. Please run fsck</b> message appeared sometimes. This was caused by a dirty bit on the file system. The fix ensures that controllers work as expected. This issue was observed in controllers running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-267046	Some controllers went unresponsive due to PostgreSQL log size growth, which filled the /tmp directory. The fix ensures that PostgreSQL logs are consistently cleaned up. This issue was observed in controllers running AOS-8.10.0.17 or later versions.	AOS-8.10.0.17
AOS-267272	An error message stating <b>Read-bootinfo from LMS failed</b> appeared when trying to regroup APs in the provisioning tab under the <b>Managed Network &gt; MD name &gt; Access Points</b> page of the WebUI or after using the <b>read-bootinfo ap-name</b> and <b>airmatch ap freeze ap-name</b> commands. The issue occurred after adjusting the device path or resetting the device node on the controller. The fix ensures that the process works as expected. This issue was observed in access points running AOS-8.10.0.17 or later versions.	AOS-8.10.0.17
AOS-267969	Some AP-655 access points running AOS-8.10.0.16 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the crash as <b>Kernel panic: WLAN target issue: ar_wal_peer.c:9694 Assertion !WAL_IS_TID_QOS_DATA(tidno) failed.</b> The fix ensures that the APs work as expected.	AOS-8.10.0.16

**Table 3:** Resolved Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-268550	The driver did not perform proper clean-up after ranging failure when FTM was enabled, leaving the PHY in a deaf state. The fix ensures that the process works as expected. This issue was observed on APs running AOS-8.10.0.18 or later versions.	AOS-8.10.0.18

## Known Issues in AOS-8.10.0.20

This chapter describes the known issues observed in this release.

**Table 4:** Known Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-217948	Some APs experience issues with Wi-Fi uplink 802.1X authentication due to a conflict in certificate validity period verification. This issue is observed in APs running AOS-8.7.1.1 or later versions.	AOS-8.7.1.3
AOS-221308	The <b>execute-cli</b> command does not work as expected for some <b>show</b> commands. This issue is observed in Mobility Conductors running AOS-8.7.1.4 or later versions.	AOS-8.7.1.4
AOS-229024	Some AP-505 access points crash and reboot unexpectedly. The log files list the reason for the event as <b>PC is at wlc_mbo_parse_ie+0x15c/0x2b0 [wl_v6]</b> . This issue is observed in APs running AOS-8.7.1.5 or later versions.	AOS-8.7.1.5
AOS-229770	Controllers do not display information on the 802.1X connection statuses if the 802.1X connection fails. This issue is observed in controllers running AOS-8.7.1.8 or later versions.	AOS-8.7.1.8
AOS-232092	Some AP-305 and AP-505 access points are not discoverable by Zigbee devices. The southbound traffic is giving the error <b>AP not found</b> . This issue is observed on devices running AOS-8.8.0.1 or later versions.	AOS-8.8.0.1
AOS-232233	Some 9004-LTE controllers cache the LAN side MAC address during boot up. Thus, the gateway does not receive an IP address from the modem. This issue is observed in controllers running AOS-8.7.0.0 or later versions.	AOS-8.7.1.4
AOS-232875 AOS-239469	The <b>mon_serv</b> process crashes in certain high-load scenarios, particularly with a large number of APs and users with high roaming rates. The issue occurs in Mobility Controllers running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-237174	Some 9240 controllers record informational logs, even though the system log level is configured as <b>warning</b> . This issue is observed in controllers running AOS-8.10.0.2 or later versions.	AOS-8.10.0.2
AOS-238407	AppRF application or application category ACL is not blocking YouTube on devices connected to APs running AOS-8.6.0.16 or later versions.	AOS-8.6.0.16
AOS-238846	The <b>Exceeds the max supported vlans 128</b> error message is displayed when creating Layer 2 VLANs at folder level. This issue is observed in Mobility Conductors running AOS-8.6.0.15 or later versions.	AOS-8.6.0.15

**Table 4:** Known Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-239521	Users are unable to add a tunnel to a tunnel group and an error message <b>Error: All tunnels must have same vlan membership</b> is displayed. This issue occurs when the VLANs are configured in a different order when compared to the order configured for other tunnels in the same group. This issue is observed in managed devices running AOS-8.6.0.15 or later versions.	AOS-8.6.0.15
AOS-239814	In some controllers running AOS-8.6.0.11 or later versions, IPv4 and IPv6 accounting messages use the same session ID with <b>Passpoint</b> . This causes multiple accounting messages to be sent repeatedly.	AOS-8.6.0.11
AOS-242404	The reason and timestamp of APs in a <b>DOWN</b> status is not displayed in the Mobility Conductor dashboard under <b>Infrastructure &gt; Access Devices</b> . The information displayed is <b>AP is down since - because of the following reason: None</b> , or similar. This issue is observed in AOS-8.10.0.4 or later versions.	AOS-8.10.0.4
AOS-242532	Some AP-535 access points are not available on 7210 controllers post power outage. This issue occurs when a USB converter and console cable are used, which interrupts the boot up process and results in the AP not showing up on the controller. The issue is observed in controllers running AOS-8.6.0.9 or later versions.	AOS-8.6.0.9
AOS-243266	In some 7220 controllers, APs upgraded through TFTP are stuck in <b>Upgrading</b> status due to an incorrect automatic change of UDP ports. This issue is observed in Mobility Controllers running AOS-8.6.0.20 or later versions.	AOS-8.6.0.17
AOS-244193	Some AP-655 access points frequently bootstrap due to an interoperability issue of the APs firmware with certain third-party switches. The issue is observed in APs running AOS-8.10.0.6 or later versions.	AOS-8.10.0.6
AOS-244850 AOS-255408	The CLI process crashes unexpectedly on 9240 controllers running AOS-8.10.0.0 or later versions.	AOS-8.10.0.8
AOS-245367	In standalone controllers, it is not possible to configure application speed limit under the <b>Dashboard &gt; Traffic Analysis &gt; Applications</b> tab. This feature works if the controller is in Conductor role, but this error is not reported properly. This issue is observed in devices running AOS-8.10.0.5 or later versions.	AOS-8.10.0.5
AOS-246514	Some APs randomly crash and reboot. The log files list the reason as <b>Reboot caused by kernel panic: QDF BUG in target_if_dbr_replenish_ring Line 1063: Failed assertion '0'</b> . This issue is observed in AP-535 access points running AOS-8.10.0.8 or later versions. <b>Workaround:</b> Disable spectrum monitoring.	AOS-8.10.0.8
AOS-246960	Mobility Controller upgrades trigger license changes, which cause the unintended loss of configured user-roles and ACLs in managed devices. This issue is observed in 7010 controllers running AOS-8.6.0.21 or later versions. <b>Workaround:</b> Reload the managed device or restart the <b>profmgr</b> process to fix the issue.	AOS-8.6.0.21

**Table 4:** Known Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-247721	Mobility Conductors in a standby setup failover and crash unexpectedly. The log files list the reason as <b>Datapath Exception</b> . This issue is observed in Mobility Conductors running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-247807		
AOS-248466	The controller <b>discovery preference</b> field disappears when changing it from <b>ADP</b> to <b>Static</b> under the <b>Dashboard &gt; Configuration &gt; Access Point &gt; Provision</b> page of the WebUI. This issue is observed in controllers running AOS-8.10.0.8 or later versions.	AOS-8.10.0.8
AOS-248905	Clients are assigned the wrong role when reconnecting to WPA3 Enterprise (GCM) SSIDs, in both CNSA and non-CNSA modes. The issue is related to PMK caching as part of dot1x authentication. This issue is observed in controllers running AOS-8.10.0.0 or later versions. <b>Workaround:</b> Since this is a PMK caching issue, clearing the cache by using the <b>aaa authentication dot1x key-cache clear &lt;unk&gt;station-mac</b> command solves the problem.	AOS-8.10.0.0
AOS-253146		
AOS-254328	WLANS with any upper-case characters created from the CLI or WebUI cannot be edited through the <b>Configuration &gt; WLANS</b> section of the WebUI. This issue is observed in Mobility Conductors running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11
AOS-255629	The bandwidth contract profile reference is not updated correctly when used in other profiles, such as role or user. This issue is observed in managed devices running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-256229		
AOS-256633	Default roles on some controllers, such as the authenticated role, are lost after enabling the <b>PEF</b> feature. This occurs because the role configurations are not retained when the feature is enabled. This issue is observed in controllers running AOS-8.10.0.9 or later versions. <b>Workaround:</b> After performing a <b>write erase</b> operation, enable the <b>PEF</b> feature and reload the controller to ensure that the default roles are initialized properly. This workaround is also applicable whenever the PEF license is used on the controller for the first time.	AOS-8.10.0.9
AOS-256450		
AOS-255529	The <b>Delete</b> option is missing for the first four WLANS listed in the WebUI of the Mobility Conductor. This issue is observed in managed devices running AOS-8.10.0.8 or later versions in a Mobility Conductor-Managed Device topology.	AOS-8.10.0.8
AOS-256636	When PAPI security is enabled, the dot1x-process fails to verify PAPI checksum for messages received from APs. However, when control plane security is disabled for APs, mobile devices and APs can communicate as plain text. This issue is observed in APs running AOS-8.6.0.15 or later versions. <b>Workaround:</b> Enable control plane security and do not use enhanced security.	AOS-8.6.0.15
AOS-257647	The <b>PhoneHome</b> CLI commands are still available and generate log entries despite the feature being disabled. This issue is observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0

**Table 4: Known Issues in AOS-8.10.0.20**

Bug ID	Description	Reported Version
AOS-259078	<p>By design, a capacity license cannot be added through the WebUI whenever an external license server is configured. However, the <b>Configuration &gt; License &gt; Capacity License</b> tab is visible. This issue is observed in managed devices running AOS-8.10.0.0 or later versions.</p> <p><b>Note:</b> Capacity licenses should be added through the CLI of managed devices.</p>	AOS-8.10.0.0
AOS-259743	<p>Some APs go down when removing the <b>interface GigabitEthernet 0/0/1</b> command, causing a state change in the Cluster and the Virtual Router Redundancy Protocol (VRRP). This issue is observed in devices running AOS-8.10.0.6 or later versions.</p>	AOS-8.10.0.6
AOS-260012	<p>Under the <b>Dashboard &gt; Configuration &gt; Roles &amp; Policies &gt; Roles</b> page, the <b>RULES</b> field incorrectly displays -- when <b>Policy-Based Routing</b> is enabled. This issue occurs because of a case mismatch between the policy names received from the API. This issue is observed in managed devices running AOS-8.10.0.14 or later versions.</p>	AOS-8.10.0.14
AOS-260519	<p>Stale entries are not cleared in the WebUI when the <b>clear gap-db</b> command is executed for the AP. This issue occurs due to the SC-MON process not being able to clear down AP entries successfully. This issue is observed in APs running AOS-8.10.0.6 or later versions.</p>	AOS-8.10.0.6
AOS-260567 AOS-261845 AOS-263055	<p>Stale APs remain visible in the Mobility Conductor's UI due to SC-MON not receiving the deletion notification from SAPM. This issue occurs when the initial notification from SAPM is missed, and manual clears fail to reach SC-MON. This issue is observed in devices running AOS-8.10.0.15 or later versions.</p>	AOS-8.10.0.15
AOS-260698	<p>In some 9240 gateways, adding a capacity license in the WebUI fails if the key contains a plus sign (+). Verifying the license in the CLI also reveals the license is not installed. However, installing the license directly in the CLI works as expected. This issue is observed in controllers running AOS-8.10.0.11 or later versions.</p> <p><b>Note:</b> Capacity licenses should be added through the CLI of managed devices.</p>	AOS-8.10.0.11
AOS-261426	<p>The <b>serpappstart</b> process crashes in some 7210 controllers running AOS-8.10.0.12 or later versions.</p> <p><b>Workaround:</b> Increase the waiting/sync time and configure the nanny process to restart <b>serpappstart</b>.</p>	AOS-8.10.0.12
AOS-261946	<p>Some AP-550 access points crash and reboot unexpectedly after upgrading from AOS-8.7.1.6-FIPS to AOS-8.10.0.14-FIPS. The log files list the reason for the crash as <b>Reboot caused by kernel panic: Take care of the TARGET ASSERT first</b>. This issue is observed in devices running AOS-8.10.0.14 or later versions.</p>	AOS-8.10.0.14
AOS-262031	<p>On warm start (wlsxWarmStart) or cold start (wlsxColdStart) of gateways, the Aruba WLSX-TRAP-MIB defined traps are not sent, but the standard SNMPv2-MIB traps (warmStart, coldStart) are sent correctly. This issue is observed in controllers running AOS-8.10.0.12 or later versions.</p>	AOS-8.10.0.12

**Table 4: Known Issues in AOS-8.10.0.20**

Bug ID	Description	Reported Version
AOS-262137	Some AP-535 access points running AOS-8.10.0.4 or later versions crash and reboot unexpectedly. The log files list the reason for the event as <b>Reboot caused by kernel panic: Take care of the TARGET ASSERT first.</b>	AOS-8.10.0.4
AOS-262497	SHA-512 encryption is not supported in DDNS, causing issues with services like Infoblox. This issue is observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.10.0.11
AOS-264047	When adding an authentication server under the <b>Captive Portal profile</b> via the WebUI, the server list reverts to the default group after submission. This occurs because the custom server group is unintentionally deleted during add/modify/remove operations, causing the system to revert to the default server group. This issue is observed in devices running AOS-8.10.0.15 or later versions.	AOS-8.10.0.15
AOS-264492	After an unexpected reboot, some managed devices are not displayed in the output of the <b>show mon-serv-lc-table</b> command. This issue is observed in devices running AOS-8.10.0.14 or later versions. <b>Workaround:</b> Run the <b>process restart mon_serv</b> command on the conductor.	AOS-8.10.0.14
AOS-265453	Some access points show a dirty flag after migrating from 7030 to 9012 controllers. This issue occurs because 9012 controllers can only support a maximum of 32 APs when running AOS-8.10.x.	AOS-8.12.0.5
AOS-265548	Some 9004 controllers are unable to forward ARP requests towards a specific IP address despite being connected to the same L2 domain. This issue occurs because the NAT pool function is using an incorrect byte order. The issue is observed in controllers running AOS-8.10.0.15 or later versions.	AOS-8.10.0.15
AOS-266876	Some 7240M gateways in FIPS mode are experiencing around 100% CPU usage during the <b>login-fcgi</b> process. This issue is observed in devices running AOS-8.10.0.16 or later versions.	AOS-8.10.0.16
AOS-268285	VLAN interfaces configured with IP addresses containing <b>127</b> as the second octet experience reachability issues. This occurs because the IP addresses are incorrectly identified as loopback addresses due to an endianness issue. This issue is observed in 9240 controllers running AOS-8.10.0.16-FIPS or later versions.	AOS-8.10.0.16
AOS-268298	In some Mobility Controllers, the <b>disable-ftp-server</b> option does not work correctly, causing Port 21 to remain open. This issue is observed on devices running AOS-8.10.0.15 or later versions.	AOS-8.10.0.5
AOS-268823	Mesh links are sometimes disconnected due to <b>meshd_read_wlan_packet</b> consuming corrupt frames, which happens infrequently and the link recovers on its own. This issue is observed in devices running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-259662	Some AP-635 access points running AOS-8.10.0.14 or later versions, experience assertion errors and reboot unexpectedly. The log files list the reason as <b>wlan_wmi.c:653 Assertion 0 failedparam0 :zero, param1 :zero, param2 :zero.</b>	AOS-8.10.0.14

**Table 4:** Known Issues in AOS-8.10.0.20

Bug ID	Description	Reported Version
AOS-268958	Mesh links stability is occasionally affected in devices running AOS-8.10.0.0 or later versions. This occurs due to the way that capabilities of peer mesh devices are periodically evaluated by the <b>meshd</b> process.	AOS-8.10.0.0

# Chapter 7

## Limitations in AOS-8.10.x

---

This section includes the known limitations in 8.10.x.x releases.

Title	Description
Port-Channel Limitation in 7280 Controllers	<p>The 7280 hardware architecture consists of two Network Acceleration Engines (NAEs). The ethernet ports are split between the NAEs according to this mapping:</p> <ul style="list-style-type: none"><li>■ NAE 0: Ports 0/0/4 to 0/0/7 and 0/0/12 to 0/0/15</li><li>■ NAE 1: Ports 0/0/0 to 0/0/3 and 0/0/8 to 0/0/11</li></ul> <p>When configuring a port-channel, it is recommended that member ports are distributed between the two different NAEs (e.g., 0/0/0 and 0/0/4). This is to ensure hitless operation if one of the member ports experiences a link flap either due to a network event or a user-driven action. If member ports are on the same NAE, a link flap will be observed for less than a second. It is not recommended to form a 10 Gbe based port-channel larger than 2x 10 Gbe due to this hardware limitation.</p>
No Support for Airtime Fairness Mode	Airtime Fairness Mode is not supported in 802.11ax access points.
6 GHz Channel Information in Regulatory Domain Profile	<p>AOS-8 does not display the 6 GHz channel information in the existing regulatory domain profile of Wi-Fi 6E APs by default.</p> <p>To include 6 GHz channel information, ensure that you change the country code to a different country code, apply the change, and then revert it to the original country code. Another option is to create a new regulatory domain profile that includes the 6 GHz channel information by default, or copy the existing regulatory domain profile into a new regulatory domain profile to save the configuration.</p> <p>The following example configures a regulatory domain profile and specifies a valid 6 GHz band.</p> <div style="background-color: #f0f0f0; padding: 10px;"><pre>(host) [mynode] (config) #ap regulatory-domain-profile reg-635 (host) [mynode] (Regulatory Domain profile "reg-635") #country-code US (host) [mynode] (Regulatory Domain profile "reg-635") #valid-6ghz- channel 165</pre></div>
Limitations in 650 Series and 630 Series Access Points	<ul style="list-style-type: none"><li>■ No spectrum analysis on any radio</li><li>■ No Zero-Wait DFS</li><li>■ No Hotspot and Air Slice support on the 6 GHz radio</li><li>■ No 802.11mc responder and initiator functionality on any radio</li><li>■ Only 4 VAPs on the 6 GHz radio instead of 16</li><li>■ Maximum of 512 associated clients on any radio, instead of 1024</li></ul>
Air Slice is partially enabled on some 500 Series APs	Air Slice is partially enabled on 500 Series access points and 510 Series access points. However, WMM boost will be functional even if Air Slice high-priority queuing is disabled.

Title	Description
<b>cpboot</b> command in 7000 Series and 7200 Series Controllers	The <b>cpboot</b> command does not upgrade the AOS-8 software version of 7000 Series and 7200 Series controllers.
VAP Limitation on Access Point Platforms	When performing configuration changes on one VAP, clients associated to other non-modified VAPs may lose connectivity. This issue is observed in 340 Series (344/345), 500 Series (503/504/505), 500H Series (503H/505H), 500R Series (503R), 510 Series (514/515/518), 560 Series (565/567), 560EX Series (565EX/567EX), 570 Series (574/575/577), 570EX Series (575EX/577EX), 600H Series (605H), 600R Series (605R), and 610 Series (615) access points running AOS-8.3.0.0 or later versions. For more information, contact support and make reference to bug ID AOS-131599.
Multiple DHCP Servers Limitation	When multiple ports with different DHCP servers are set up, the device will accept the first DHCP IP address it receives and apply that configuration, overriding any previous settings. To avoid conflicts, only one primary port should be configured for DHCP.

# Chapter 8

## Upgrade Procedure

---

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



Read all the information in this chapter before upgrading your Mobility Conductor, managed device, or stand-alone controller.

---

### Important Points to Remember

To upgrade your managed device or Mobility Conductor:

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
  - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
  - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
  - What version of AOS-8 runs on your managed device?
  - Are all managed devices running the same version of AOS-8?
  - What services are used on your managed device (employee wireless, guest access, Remote AP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load AOS-8 images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of AOS-8, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Aruba Mobility Conductor Licensing Guide*.
- With the introduction of the Long Supported Release (LSR) and Short Supported Release (SSR) terminology in AOS-8.10.0.0, a Mobility Conductor running an LSR release supports managed devices running the same release and the three preceding releases. This is considered as N-3 support. This allows a customer to run the latest LSR, the previous SSRs and the previous LSR simultaneously. A Mobility Conductor running an SSR release supports managed devices running the same release and the two preceding releases. This would be considered N-2 support and is the same behavior as the pre-AOS-8.10.0.0 MultiVersion support.

- Only for the AOS-8.10.0.0 LSR release, AOS-8.6.0.0 is treated as an LSR despite being beyond N-3. As such a Mobility Conductor running AOS-8.10.0.0 supports managed devices running AOS-8.10.0.0, AOS-8.9.0.0, AOS-8.8.0.0, AOS-8.7.0.0 and AOS-8.6.0.0.

## RAM and FLASH Storage Requirements

All Aruba managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Ensure sufficient RAM and flash space is available in the Controller/MD/BGW before proceeding with the upgrade.
- Execute the **show memory** command to identify the available free memory.
- Execute the **show storage** command to identify the available flash space.
- If the output of the **show storage** command indicates that there is insufficient flash RAM, free some used memory. Copy any log files, crash data, or flash backups from your gateways to a desired location. Delete the following files from the Controller/MD/BGW to free FLASH storage:
  - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 29](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
  - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 29](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
  - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 29](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device
- The show commands are available under **Analyze > Tool > Commands** section of Aruba Central.

If available RAM is not sufficient to meet the requirements stated in the appropriate release notes, it may be necessary to reboot the device and then immediately upgrade, or disable some functionality. The user should consult HPE/Aruba technical support for guidance.



---

In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

---

### Deleting a File

You can delete a file using the WebUI or CLI.

#### In the WebUI

From the Mobility Conductor, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

#### In the CLI

```
(host) #delete filename <filename>
```

## Low Free Flash Memory

Sometimes, after extended use, the flash memory might get used up for logs and other files. The AOS-8 image has increased in size and this may cause issues while upgrading to newer AOS-8 images without cleaning up the flash memory.

## Prerequisites

Before you proceed with the freeing up the flash memory:

- Ensure to always backup the configuration and flash memory. Issue the **backup configuration** and **backup flash** commands to backup the configuration and flash.
- Copy the **flashbackup.tar.gz** and **configbackup.tar.gz** files out of the controller. Then delete the **flashbackup.tar.gz** and **configbackup.tar.gz** files from the flash memory of the controller.
- Use only one partition for the upgrade activity and keep the other partition unchanged.

If you use the WebUI to perform an upgrade, a banner on the **Maintenance** page provides the following reminder to have sufficient free flash memory before initiating an upgrade.

**For a healthy and stable system it requires free space of 360 MB for AOS v8.3 and 8.5, 570 MB for AOS 8.6 and 8.7 and 450 MB for AOS 8.8 and higher version in the /flash directory. Please make sure minimum required memory is available in /flash before upgrading to newer version.**

## Freeing up Flash Memory

The following steps describe how to free up the flash memory before upgrading:

1. Check if the available memory in **/flash** is greater than the limits listed in [Table 5](#) for all supported controller models:

**Table 5: Flash Memory Requirements**

Upgrading from	Upgrading to	Minimum Required Free Flash Memory Before Initiating an Upgrade
8.3.x	8.10.x	360 MB
8.5.x	8.10.x	360 MB
8.6.x	8.10.x	570 MB
8.7.x	8.10.x	570 MB
8.8.x	8.10.x	450 MB
8.9.x	8.10.x	450 MB
8.10.x	8.10.x	450 MB

To check the available free flash memory, issue the **show storage** command. Following is the sample output from a controller with low free flash memory:

```
(host) [mynode] #show storage
Filesystem          Size    Available     Use    % Mounted on
/dev/usb/flash3     1.4G    1014.2M     386.7M  72%    /flash
```

2. If the available free flash memory is less than the limits listed in [Table 5](#), issue the following commands to free up more memory.

- **tar crash**
- **tar clean crash**
- **tar clean logs**
- **tar clean traces**

3. Issue the **show storage** command again to check if the available space in **/flash** is more than the minimum space required for AOS-8 upgrade as listed in [Table 5](#)
4. **If you are unable to free up sufficient flash memory, contact Technical Support. Do not reboot the controller.**
5. If sufficient flash memory is available, proceed with the standard AOS-8 upgrade. See [Upgrading AOS-8](#).
6. If a reboot was performed, you may see some of the following errors. Follow the directions below:
  - Upgrade using standard procedure. You may see some of the following errors:
 

**Error upgrading image: Ancillary unpack failed with tar error ( tar: Short header ).**  
**Please clean up the /flash and try upgrade again.**

**Error upgrading image: Ancillary unpack failed with tar error ( tar: Invalid tar magic ).**  
**Please clean up the /flash and try upgrade again.**

**Error upgrading image: Need atleast XXX MB space in /flash for image upgrade, please clean up the /flash and try upgrade again.**

**Failed updating: [upgradeImageNew.c] extractAncTar (dev: /dev/usb/flash1 imgLoc: /flash/config/ArubaOS\_70xx\_8.8.0.0-mm-dev\_78066**

- If any of the above errors occur, issue the **show image version** command to check for the default boot partition. The partition which was upgraded should become the default partition.

Following is the sample output of the **show image version** command:

```
(host) [mynode] #show image version
-----
Partition          : 0:0 (/dev/usb/flash1) **Default boot**
Software Version  : AOS-8.9.0.0 (Digitally Signed SHA1/SHA256 - Production
Build)
Build number      : 81046
Label              : 81046
Built on          : Thu Aug 5 22:54:49 PDT 2021
-----
Partition          : 0:1 (/dev/usb/flash2)
Software Version  : AOS-8.7.0.0-2.3.1.0 (Digitally Signed SHA1/SHA256 -
Developer/Internal Build)
Build number      : 0000
Label              : arpitg@sdwan-2.3_arpitg-3-ENG.0000
Built on          : Tue Aug 10 15:02:15 IST 2021
```

- If the default boot partition is not the same as the one where you performed the upgrade, change the default boot partition. Issue the **boot system partition <part\_number>** command to change the default boot partition. Enter **0** or **1** for **part\_number** representing partition 0:0 or partition 0:1, respectively.
- Reload the controller. If any of the errors listed in step 4 were observed, the following errors might occur while booting AOS-8.9.0.0.

Sample error:

```
[03:17:17]:Installing ancillary FS [ OK ]
Performing integrity check on ancillary partition 1 [ FAIL : Validating new
ancillary partition 1...Image Integrity check failed for file
/flash/img1/mswitch/sap/arm32.ari. Digest Mismatch]
```

```
Extracting Webui files..tar: Short read
chown: /mswitch/webui/*: No such file or directory
chmod: /mswitch/webui/wms/wms.cgi: No such file or directory
```

- After the controller reboots, the login prompt displays the following banner:

```
*****
* WARNING: An additional image upgrade is required to complete the *
* installation of the AP and WebUI files. Please upgrade the boot   *
* partition again and reload the controller.                         *
*****
```

- Repeat steps 1 through 5. If sufficient free flash memory is available, proceed with the standard AOS-8 upgrade procedure. See [Upgrading AOS-8](#).
- If sufficient free flash memory is not available, issue the **dir** and **dir flash** commands to identify large files occupying the flash memory.



- Exercise caution while deleting files. Contact Technical Support if you are not sure which large files in the **/flash** directory could be safely deleted to free up the required space.

Issue the **delete filename <filename>** command to delete large files to free more flash memory.

- Check if sufficient flash memory is free as listed in [Table 5](#).
- Proceed with the standard AOS-8 upgrade procedure in the same partition. See [Upgrading AOS-8](#).

## Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

## Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

### In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Conductor node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

## In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
```

Please wait while we take the flash backup.....

File flashbackup.tar.gz created successfully on flash.

Please copy it out of the controller and delete it when done.

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword> <remote directory>
```

```
(host) #copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
```

Please wait while we restore the flash backup.....

Flash restored successfully.

Please reload (reboot) the controller for the new files to take effect.

## Upgrading AOS-8

Upgrade AOS-8 using the WebUI or CLI.



Ensure that there is enough free memory and flash space on your Mobility Conductor or managed device. For details, see [RAM and FLASH Storage Requirements on page 26](#).



When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

## In the WebUI

The following steps describe how to upgrade AOS-8 from a TFTP server, FTP server, or local file.

1. Download the AOS-8 image from the customer support site.
2. Upload the AOS-8 image to a PC or workstation on your network.
3. Validate the SHA hash for the AOS-8 image:
  - a. Download the **Aruba.sha256** file from the download directory.

- b. Load the AOS-8 image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
- c. Verify that the output produced by this command matches the hash value found on the customer support site.

 The AOS-8 image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Conductor or managed device will not load a corrupted AOS-8 image.

4. Log in to the AOS-8 WebUI from the Mobility Conductor.
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
  - a. Select the **Local File** option from the **Upgrade using** drop-down list.
  - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.

 The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Conductor or managed device reboots automatically.

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

## In the CLI

The following steps describe how to upgrade AOS-8 from a TFTP server, FTP server, or local file.

1. Download the AOS-8 image from the customer support site.
2. Open an SSH session to your Mobility Conductor.
3. Execute the **ping** command to verify the network connection between the Mobility Conductor and the SCP server, FTP server, or TFTP server.

```
(host) # ping <ftphost>
```

or

```
(host) # ping <tftphost>
```

or

```
(host) # ping <scphost>
```

4. Execute the **show image version** command to check if the AOS-8 image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

5. Execute the **copy** command to load the new image to the non-boot partition.

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host) # copy scp: <scphost> <scphost> <image filename> system: partition <0|1>
```

or

```
(host) # copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

6. Execute the **show image version** command to verify that the new image is loaded.

```
(host) # show image version
```

7. Reboot the Mobility Conductor.

```
(host) #reload
```

8. Execute the **show version** command to verify that the upgrade is complete.

```
(host) #show version
```

## Verifying the AOS-8 Upgrade

Verify the AOS-8 upgrade in the WebUI or CLI.

### In the WebUI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the AOS-8 image version.
2. Verify if all the managed devices are up after the reboot.
3. Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
4. Verify that the number of APs and clients is as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 29](#) for information on creating a backup.

### In the CLI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the CLI to verify that all your managed devices are up after the reboot.
2. Execute the **show version** command to verify the AOS-8 image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 29](#) for information on creating a backup.

## Downgrading AOS-8

A Mobility Conductor or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Conductor or managed device from the other partition.

### Pre-requisites

Before you reboot the Mobility Conductor or managed device with the pre-upgrade AOS-8 version, perform the following steps:

1. Back up your Mobility Conductor or managed device. For details, see [Backing up Critical Data on page 29](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Conductor or managed device to boot with the previously saved configuration file.
4. Set the Mobility Conductor or managed device to boot from the partition that contains the pre-upgrade AOS-8 version.

When you specify a boot partition or copy an image file to a system partition, Mobility Conductor or managed device checks if the AOS-8 version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the AOS-8 version and configuration files.

5. After switching the boot partition, perform the following steps:

- Restore the pre-upgrade flash backup from the file stored on the Mobility Conductor or managed device. Do not restore the AOS-8 flash backup file.
- Do not import the WMS database.
- If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded AOS-8 version.
- If any new certificates were added in the upgraded AOS-8 version, reinstall these certificates in the downgraded AOS-8 version.

Downgrade AOS-8 version using the WebUI or CLI.

## In the WebUI

The following steps describe how to downgrade the AOS-8 version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Conductor or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
  - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.
  - b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
  - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade AOS-8 version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade AOS-8 version is not stored on your system partition, load it into the backup system partition by performing the following steps:



---

You cannot load a new image into the active system partition.

---

- a. Enter the FTP or TFTP server address and image file name.
- b. Select the backup system partition.
- c. Enable **Reboot Controller after upgrade**.
- d. Click **Upgrade**.

3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.

The Mobility Conductor or managed device reboots after the countdown period.

4. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-8 version by navigating to the **Maintenance > Software Management > About** page.

## In the CLI

The following steps describe how to downgrade the AOS-8 version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Conductor or managed device:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```

2. Set the Mobility Conductor or managed device to boot with your pre-upgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```

3. Execute the **show image version** command to view the partition on which your pre-upgrade AOS-8 version is stored.

```
(host) #show image version
```



---

You cannot load a new image into the active system partition.

---

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```

5. Reboot the Mobility Conductor or managed device.

```
(host) # reload
```

6. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-8 version.

```
(host) # show image version
```

## Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.